

ENGINEERING MANUFACTURING CONSTRUCTION CONTROLS

3178 West Hills Road • Philomath, OR 97370 • (541) 929-2234 • FAX (541) 929-2235

Job description CNC Mill and Lathe Programmer

Duties, expectations

- ◆ Utilize supplied MasterCam program to create CNC programs for parts to be made on Haas Mills and Turning Centers
- ♦ Maintain machines in proper working order
- ♦ Show up to work on-time every day
- De-bur and inspect parts for accuracy and uniformity
- Recognize opportunities for improved efficiency/speed with additional tooling and make recommendations for tooling purchases

CNC Programming

- Program existing and new parts as needed to support shop production needs and outside job work
- Generally, not high production runs
- Program small production runs for efficiency/repeatability

Spare part sales

Support spare parts sales with purchasing and inventory support

Skills Required

- ♦ Read Blueprints
- Strong analytical skills, precision, and sharp eye for detail
- ♦ Ability to lift 50 lbs repeatedly
- Ability to work standing on concrete floor for up to 2 ½ hours between breaks
- ♦ Good general computers skills
- Good working knowledge of mechanical components and materials
- ♦ Good organizational skills
- ♦ Team work skills
- ♦ Personal management skills